

<b>Subject:</b>  <b>BODY VIBRATION OR STEERING WHEEL SHIMMY</b>	<b>M-Tips No.:</b> MT-012/18
	<b>Last Issued:</b> 12/11/2018

## BULLETIN NOTES

This bulletin supersedes the previously issued bulletin(s) listed below. The changes are noted in Red text.

Previous M-Tips:	Date(s) Issued:
MT-046/12	2012

## APPLICABLE MODEL(S)/VINS

2000-2006 MPV	2016-2019 CX-3	2011-2019 Mazda2
2000-2005 Miata	2013-2019 CX-5	2004-2019 Mazda3
2000-2002 Millenia	2007-2012 CX-7	2006-2017 Mazda5
2001-2011 Tribute	2007-2019 CX-9	2003-2019 Mazda6
	2004-2011 RX-8	2006-2019 MX-5

## DESCRIPTION

If a vehicle has body vibration or steering wheel shimmy while driving and the root cause is determined to be tire balance, re-balance the tires using a **Hunter GSP9700** or equivalent balance machine.

If your dealer does not have a GSP9700 or equivalent balance machine, sublet the vehicle out for repair. To find the location of a GSP9700 near your dealer, visit Hunter's web site at [www.gsp9700.com](http://www.gsp9700.com) and click on **"Locate a GSP9700 Road Force Balancer."**



Hunter GSP9700

An editorial board comprised of MNAO service staff members generates, collects, and verifies information for this publication.

To contribute repair tip ideas, send an e-mail to [mtips@mazdausa.com](mailto:mtips@mazdausa.com). All contributions become property of MNAO, which assumes permission to publish them without further consideration.